


# SERSIO Data -HT Low Energy Cutoff

- Decrease in flux around 400sec associated with loss of thermal core
- Suspected detector cutoff
- Cutoff due to charging or instrument design?



TOF=364sec, Peak=1.9V

TOF=401sec, Peak=1.5V

TOF=441sec, Peak=2V

